



MINI COUNTRYMAN

Mini Cooper D Countryman All4

VIN NO WMWYU110603E28293
Registration Number 0603E28293



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-10-01	1	2	183237 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-10-28	163236	2017-11-22	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250825101110
Inspection Date / Place	2025-08-25 / BCA Oberndorf	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	Sedan	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	127
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Airbag Status	Ambientlighting	Auxiliary Socket
Diesel particulate filter	Remote adjusting wing mirrors	Roof rails	Stability control
Electrically folding wing mirrors	LED Headlamps	Rear parking sensors	USB Socket
Alloys wheels	Anti-lock braking	Bluetooth telephone interface	Front fog lamps
Remote central locking	Split folding rear seats	Central locking	Leather steering wheel

Radio

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Seat Heating	No		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage


7 Schäden



1 Schäden



Component	Damage	Comments
1 Other	Anomalyon Element	
2 Bumper / Front	Paint / Scratch / Line	
3 Hood	Bodywork / Dent / Dent	
4 Rim / Front Left	Paint / Stone Chip	
5 Rim / Back Left	Out of Bodywork / Scratch	
6 Trunk Upholstery / Back	Interior / Scratched	
7 Wing Stick / Back Right	Paint / Scratch / Line	
8 Rim / Front Right	Paint / Stone Chip	



1. Anomalyon Element -



2. Bumper / Front Paint / Scratch / Line -



3. Hood Bodywork / Dent / Dent -



4. Rim / Front Left Paint / Stone Chip -



5. Rim / Back Left Out of Bodywork / Scratch -



6. Trunk Upholstery / Back Interior / Scratched -



7. Wing Stick / Back Right
Paint / Scratch / Line -



8. Rim / Front Right
Paint / Stone Chip -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓
Audio Equipment	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Clutch			
Clutch Pedal Low / High	✓	Clutch Abnormal	✓
Clutch Functioning	✓		
Steering Wheel			
Flywheel Noise	✓	Steering Noise / Anomaly	✓
General			
Test Driven Status	Not Performed		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)