



Porsche Panamera (GKL): 2BDQ087

Vinnumber:	WP0ZZZ97ZNL125035	Versionname:	Panamera 4 E-hybrid 2.9i 462pk/cv 5p PDK
First Registrationdate:	13/10/2021	Fiscalpower:	
Expertise Mileage:	90586	Power Kw:	243
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		


Tyres

	275/35/21/103 Y			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				275/35 R 21 103 Y
Tyre size FR				275/35 R 21 103 Y
Tyre size RL				315/30 R 21 105 Y
Tyre size RR				315/30 R 21 105 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Service, Maintenance, Check



Backrest cover FL, Scratch(es), Acceptable



Backrest cover FR, Scratch(es), Acceptable



Bonnet, Stone chip(s), Acceptable




Bumper F, Scratch(es), Repair and paint (complete)



Windscreen moulding, Scratch(es), Acceptable




Alloy rim FL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Sill trim R, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Roof pillar R, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Panoramic roof, Broken, Replace

