

VOLKSWAGEN CRAFTER CHASSIS CABINE CRAFTER CHASSIS CABINE 35 L3 2.0 BITDI 143 FAP EURO5



VIN NO WV1ZZZ2FZD7002892 Registration Number CM768VX

MOT Date

Number of Owners

Number of Keys

Odometer Reading

₩-

:::-

P2

2337857 km

Last Service

Last Service Mileage

First Registration Date

Country First Registered

=-

A-

2012-11-14

France

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250627152826
Inspection Date / Place	2025-06-27 / BCA AUNAY	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	2
Body Type	Platform Cab	Drive Train	Rear
Seat Colour		No of Seats	3
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	224

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			

















Equipment


Central locking Anti-lock braking Remote central locking Radio

Power assisted steering

Equipment Details

Seat Heating No Air Conditioning No

Cosmetic Damage





1. Mirror / Front Left Missing Part -

2. Mirror / Front Right Missing Part -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut



- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- Not tested

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.