

VW CADDY SKÅPBIL 1.9 TDI

Vehicle information

License plate	GMO609	Inspected by	M.H.
Year model	2008	Date of inspection	2025-03-12
Manuf. year/month	-	City	Sundsbruk
First day in traffic	2007-11	Keys	2
Colour	Vit	Service book	Saknas
Mileage	101 200 km	Latest service	-
Fuel	Diesel	Mileage at the latest service	-
Transmission	Manuell	Summer tires	15" plåtfälg 5/4/4/3
Engine effect	77 kW	Winter tires	15" plåtfälg 8/8/8/8

Damages

Location	Damage	Comments	Costs excluding VAT
Service	Servicebook missing		460 €
Rims & Tires, Winter	Rim damage 4 wheel		550 €
Bumper, Rear	Cargo scratches		180 €
Sills, Right	Paint damages	Rost	460 €
Wing, Front right	Dents 30-100 mm		320 €
Bonnet	Chips, several		200 €
Sills, Left	Paint damages		460 €
Total excl. VAT			2 630 €

Images

[See all images in large format](#)























Stötfångare Bak Lastrepör 2 000 kr



Trösklar Höger Lackskador Rost 5 000 kr



Skärm Höger fram Bucklor 3-10 cm 3 500 kr



Motorhuv Stenskott flertal 2 200 kr



Trösklar Vänster Lackskador 5 000 kr