

Inspection Protocol



VW CADDY SKÅPBIL 1.6 TDI

Vehicle information

License plate	LUZ233	Inspected by	M.H.
Year model	2012	Date of inspection	2025-04-11
Manuf. year/month	2011-06	City	Sundsbruk
First day in traffic	2011-07	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	118 210 km	Latest service	-
Fuel	Diesel	Mileage at the latest service -	
Transmission	Manuell	Summer tires	15" plåtfälg 4/4/4/6
Engine effect	55 kW	Winter tires	15" plåtfälg 6/6/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Engine and Transmission, Motor	Noise	Misständer	-
Lamps, Headlights	No light	Vänster fram lyser ej	30 €
Recond	Traces of decals		70 €
Rims & Tires, Winter	Rim damage 4 wheel		540 €
Recond	Interior		70 €
Bumper, Rear	Cargo scratches		180 €
Door, Right sliding door	Scratches below 30 mm		70 €
Bonnet	Pitted		330 €
Other, Other	Regskylt fram inbuktningar	Nummer skylt fram saknas	90 €
Inredning, Drivers seat	Tears		180 €
Total excl. VAT			1 560 €

Service occasions

10000-MIL, 11000-MIL

Images

[See all images in large format](#)















