

Inspection Protocol

TRADING
SOLUTIONS

VW CADDY MAXI 2.0 TDI BLUEMOTION

Vehicle information

License plate	UDR482	Inspected by	C.C.
Year model	2018	Date of inspection	2025-03-12
Manuf. year/month	2018-02	City	Björkvik
First day in traffic	2018-03	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	160 730 km	Latest service	-
Fuel	Diesel	Mileage at the latest service -	
Transmission	Manuell	Summer tires	15" plåtfälg 3/3/3/3
Engine effect	75 kW	Winter tires	plåtfälg dubbat 6/6/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Recond	Interior		60 €
Bumper, Rear	Cargo scratches		150 €
Lamps, Bakljus	Cracks glass	Höger bak	-
Boot lid, Right transport door	Other	Saknas vw märke	-
Wing, Rear right	Paint damages		-
Door, Righ side mirror	Scratches below 30 mm		60 €
Wing, Front right	Scratches below 30 mm		60 €
Bumper, Front	Repor, 3-10 cm		80 €
Glass, Windshield	Chip		20 €
Total excl. VAT			430 €

Service occasions

3000-MIL, 7000-MIL, 10000-MIL, 13000-MIL, 16000-MIL

Images

[See all images in large format](#)















Rekond Invändig 800 kr










Stötfångare Bak Lastrepör 2 000 kr



Lampor Bakljus Sprickor glas Höger bak



Bagagelucka Höger transportdörr Övrigt Saknas vw märke



Skärm Höger bak Lackskador





Dörr Höger backspegel Repor under 3 cm 800 kr



Skärm Höger fram Repor under 3 cm 800 kr



Stötfångare Fram Repor, 3-10 cm 1 100 kr





Glas Vindruta Stenskott 300 kr







