

DEKRA Automotive Solutions

Vehicle details

VIN	WV1ZZZ2KZ KX070474	Brand	VOLKSWAGEN	Maintenance date	29/04/2025
Licence Plate	KSN29S	Model	Caddy-LCV-SA-2015	Maintenance mileage	129 007 km
Registration date	15/08/2019	Year	2019	Exterior Color	Other
Odometer	131 344 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	6		

Inspection Details

Inspection date	02/10/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Bluetooth	✓
Reversing radars	✓
Automatic Gearbox	✓
Central locking	✓
4x4	✓
Park Distance Control	✓
Audio System	✓

Removable element

Refill emergency kit	✓
----------------------	---

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓

DEKRA Automotive Solutions

Tyres

Continental 205/55/16 H Summer 4.0 mm		Continental 205/55/16 H Summer 4.0 mm	
Continental 205/55/16 H Summer 4.0 mm		Continental 205/55/16 H Summer 4.0 mm	

Winter kit

Nokian 205/55/16 T Winter 4.0 mm		Nokian 205/55/16 T Winter 4.0 mm	
Nokian 205/55/16 T Winter 6.0 mm		Nokian 205/55/16 T Winter 6.0 mm	

Damages

1



Part	Complete service track record
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum

2



Part	Other mechanical
Position	-
Damages	Defective
Severity	-
Repair mode	For info
Ac unit not cooling	

3



Part	Other mechanical
Position	-
Damages	Defective
Severity	-
Repair mode	For info
Steering play	

4



Part	Bumper grille
Position	Front
Damages	Pierced
Severity	-
Repair mode	Replace

5



Part	Door
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info

6



Part	Wing
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

7



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

8



Part	Bonnet
Position	Front
Damages	Stone impact
Severity	-
Repair mode	For info

9



Part	Roof
Position	-
Damages	Dented
Severity	-
Repair mode	For info

10



Part	Steering wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

DEKRA Automotive Solutions

11		Part	Other mechanical
		Position	-
		Damages	Defective
		Severity	-
		Repair mode	For info
		Breaking vibrations during test drive	