



Volkswagen Caddy: VBN12S

Vinnumber:	WV1ZZZ2KZKX105525	Versionname:	Caddy Maxi 1.4 TGI Ecofuel 81kW
First Registrationdate:	29/10/2019	Fiscalpower:	
Expertise Mileage:	202275	Power Kw:	81
Bodytype:		Body colour	Candywit
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Gas	Parking lot	872
Number of seats	2		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2	Rear parking sensors
Number keys remote	2	Sliding door right-side
Windows electric F		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 65 / 15 / 95 / V / Steel	6,3 mm	Continental	All season
	Right	195 / 65 / 15 / 95 / V / Steel	6,2 mm	Continental	All season
Rear	Left	195 / 65 / 15 / 95 / V / Steel	5,8 mm	Michelin	All season
	Right	195 / 65 / 15 / 95 / V / Steel	4,2 mm	Michelin	All season

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Seat cover FL, Worn, Replace



Backrest cover FL, Worn, Replace



Floor covering, Worn, Replace



Centre console, Scratch(es), Replace



Dashboard, Scratch(es), Smart repair



Seat cover FR, Worn, Replace



Wing FL, Scratch(es), Repair and paint (complete)



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Smart repair



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Sliding door R, Bad repair, Repair and paint (complete)



Door FR, Bad repair, Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Boot door lining R, Broken, Replace



Boot carpet, Worn, Replace



Roof, Rust, Repair and paint (complete)

