



Volkswagen Caddy: VBT85V

Vinnumber:	WV1ZZZ2KZKX111883	Versionname:	Caddy Maxi 1.4 TGI Ecofuel 81kW
First Registrationdate:	27/11/2019	Fiscalpower:	
Expertise Mileage:	191050	Power Kw:	81
Bodytype:		Body colour	Candywit
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Gas	Parking lot	945
Number of seats	2		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
Windows electric F		Rear parking sensors
Radio multimedia		Sliding door right-side

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 65 / 15 / 95 / H / Steel	5,4 mm	Continental	Winter
	Right	195 / 65 / 15 / 95 / H / Steel	5,8 mm	Continental	Winter
Rear	Left	195 / 65 / 15 / 95 / H / Steel	5,2 mm	Hankook	Winter
	Right	195 / 65 / 15 / 95 / H / Steel	6,3 mm	Hankook	Winter

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

User's manual, Missing, Replace

No pictures to display

Seat cover FR, Tear, Replace



Interior, Stain, Chemical cleaning



Seat, Worn, Replace



Steering wheel, Worn, Replace



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing FL, Dent(s), Repair and paint (complete)



Outer sill L, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Bonnet, Dent(s), Repair and paint (complete)



Headlight R, Broken, Replace



Bumper F, Scratch(es), Smart repair



Bumper grille FR, Deformed / Strained, Replace



Headlight L, Scratch(es), Replace



Wing FR, Dent(s), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Hub cap FR, Missing, Replace



Supplementary brake light, Broken, Replace



Bumper R, Scratch(es), Smart repair



Bull bar R, Dent(s), Replace

