



Volkswagen Caddy: VBT08X

Vinnumber:	WV1ZZZ2KZKX113118	Versionname:	Caddy Maxi 1.4 TGI Ecofuel 81kW
First Registrationdate:	29/11/2019	Fiscalpower:	
Expertise Mileage:	189480	Power Kw:	81
Bodytype:		Body colour	Candywit
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Gas	Parking lot	1154
Number of seats	2		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Rear parking sensors
Windows electric F		Sliding door right-side
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 65 / 15 / 95 / V / Steel	4,0 mm	Continental	All season
	Right	195 / 65 / 15 / 95 / V / Steel	4,2 mm	Continental	All season
Rear	Left	195 / 65 / 15 / 95 / V / Steel	6,0 mm	Continental	All season
	Right	195 / 65 / 15 / 95 / V / Steel	7,2 mm	Continental	All season

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Roof liner, Stain, Cleaning



Backrest cover FR, Hole, Replace



Seat, Worn, Replace





Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace



Outer sill L, Scratch(es), Repair and paint (complete)



Bumper F, Broken, Replace



Bumper grille FL, Deformed / Strained, Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Replace



Boot door lining L, Crack, Replace



Bumper R, Scratch(es), Smart repair



Bull bar R, Dent(s), Replace



Supplementary brake light, Crack, Replace

