



Volkswagen Caddy: VDB60J

Vinnumber:	WV1ZZZ2KZX115452	Versionname:	Caddy Maxi 1.4 TGI Ecofuel 81kW
First Registrationdate:	7/01/2020	Fiscalpower:	
Expertise Mileage:	214908	Power Kw:	81
Bodytype:		Body colour	Candywit
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Gas	Parking lot	306
Number of seats	2		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	1	Telephone equipment
Windows electric F		Rear parking sensors
Radio multimedia		Sliding door right-side

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 65 / 15 / 95 / T / Steel	3,2 mm	Vredestein	All season
	Right	195 / 65 / 15 / 95 / T / Steel	5,1 mm	Vredestein	All season
Rear	Left	195 / 65 / 15 / 95 / T / Steel	4,8 mm	Vredestein	All season
	Right	195 / 65 / 15 / 95 / T / Steel	5,5 mm	Vredestein	All season

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

User's manual, Missing, Replace

No pictures to display

Ignition key, Missing, Replace

No pictures to display


Seat, Worn, Replace



Wing FL, Dent(s), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)





Outside rear-view mirror L, complete, Broken, Replace



Outer sill L, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Smart repair



Bumper grille FL, Deformed / Strained, Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



[Damage Picture - 1](#)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Bull bar R, Dent(s), Replace

