

VW CADDY SKÅPBIL 1.4 TGI BLUEMOTION

Vehicle information

License plate	UMC77H	Inspected by	C.C.
Year model	2019	Date of inspection	2025-03-06
Manuf. year/month	2019-06	City	Björkvik
First day in traffic	2019-07	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	201 570 km	Latest service	-
Fuel	Gas	Mileage at the latest service-	
Transmission	Manuell	Summer tires	15" plåtfälg 3/3/4/4
Engine effect	81 kW	Winter tires	plåtfälg odubbbat 5/5/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Service, Not serviced	Missad service		360 €
Inredning, Damage	Mindre skada	Förarstol	150 €
Other, Other	Other	Höger skjutdörr går ej att öppna	-
Door, Lef side mirror	Repa/Repor		60 €
Sills, Left	Smart repair		70 €
Bumper, Rear	Liten buckla/Repor		220 €
Boot lid, Boot lid	Liten buckla/Repor		220 €
Bumper, Front	Repa/Repor		220 €
Bonnet, Bonnet	Smart repair	Stenskott	70 €
Glass, Windshield	Stenskott/Spricka		510 €
Door, Front left	Liten buckla/Repor		220 €

Total excl. VAT	2 100 €
-----------------	---------

Comments

Finns ingen skadeanmälan glas, säljes som den står

Images

[See all images in large format](#)



















Dörr Vänster fram Liten buckla/Repor 3 000 kr



Dörr Vänster backspegel Repa/Repor 800 kr



Tröskel Vänster Smart repair 1 000 kr



Stötfångare Bak Liten buckla/Repor 3 000 kr



Bagagelucka Bagagelucka Liten buckla/Repor 3 000 kr



Stötfångare Fram Repa/Repor 3 000 kr





Motorhuv Motorhuv Smart repair Stenskott 1 000 kr





Glas Vindruta Stenskott/Spricka 7 000 kr





