

Inspection Protocol



VW CADDY VAN 1.4 TGI BLUEMOTION

Vehicle information

License plate	XFT39R	Inspected by	E.B.
Year model	2019	Date of inspection	2025-04-11
Manuf. year/month	2019-06	City	Björkvik
First day in traffic	2019-07	Keys	2
Colour	Silver	Service book	Elektronisk servicebok
Mileage	36 500 km	Latest service	-
Fuel	Gas	Mileage at the latest service	-
Transmission	DSG Sekventiell	Summer tires	15" alu-fälg 7/7/7/7
Engine effect	81 kW	Winter tires	alu-fälg dubbat 5/5/5/5

Damages

Location	Damage	Comments	Costs excluding VAT
Door, Lef side mirror	Other	Skrap	-
Wing, Rear left	Scratches below 30 mm		70 €
Boot lid, Boot lid	Other	Polerbara repor	-
Door, Right sliding door	Scratches below 30 mm		70 €
Door, Front right	Other	Polerbara märken	-
Wing, Front right	Other	Skrap	-

Total excl. VAT	140 €
-----------------	-------

Images

[See all images in large format](#)





















Dörr Höger fram Övrigt Polerbara märken



Skärm Höger fram Övrigt Skrap