

Inspection Protocol



VW CADDY MAXI 2.0 TDI BLUEMOTION 4MOTION

Vehicle information

License plate	JPP88A	Inspected by	M.H.
Year model	2019	Date of inspection	2025-03-13
Manuf. year/month	2019-07	City	Sundsbruk
First day in traffic	2019-07	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	139 900 km	Latest service	-
Fuel	Diesel	Mileage at the latest service -	
Transmission	Manuell	Summer tires	15" plåtfälg 6/5/4/4
Engine effect	90 kW	Winter tires	15" plåtfälg 8/8/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Rims & Tires, Winter	Rim damage 4 wheel		440 €
Bumper, Rear	Cargo scratches		150 €
Boot lid, Boot lid	Scratches below 30 mm		60 €
Door, Front right	Dents below 30 mm		60 €
Bonnet	Chips, several		160 €
Bumper, Front	Other	Sitter ej	20 €
Bumper, Front	Wide scratch		240 €
Wing, Rear left	Dents 30-100 mm		260 €
Glass, Windshield	Cracks long (Above 150 mm)		510 €
Total excl. VAT			1 900 €

Service occasions

7500-MIL, 10000-MIL, 11000-MIL, 13000-MIL

Images

[See all images in large format](#)































Stötfångare Bak Lastrepör 2 000 kr



Bagagelucka Bagagelucka Repor under 3 cm 800 kr



Dörr Höger fram Bucklor under 3 cm 800 kr



Motorhuv Stenskott flertal 2 200 kr



Stötfångare Fram Övrigt Sitter ej 300 kr



Stötfångare Fram Skrap 3 300 kr



Skärm Vänster bak Bucklor 3-10 cm 3 500 kr



Glas Vindruta Sprickor långa (Över 15 cm) 7 000 kr