

## Vehicle details

|                   |                    |              |                            |                           |              |
|-------------------|--------------------|--------------|----------------------------|---------------------------|--------------|
| VIN               | WV1ZZZ2KZ LX120966 | Brand        | VOLKSWAGEN                 | Maintenance date          | -            |
| Licence Plate     | VG-V8-4K           | Model        | CADDY 2.0 TDI 55 kW BMT 4d | Maintenance mileage       | -            |
| Registration date | 01/10/2020         | Year         | 2020                       | Exterior Color            | Yellow Solid |
| Odometer          | 201 637 km         | Engine size  | 1968                       | interior Color            | Grey         |
| Fuel              | Diesel             | Body Type    | -                          | Next technical inspection | -            |
| Seats             | -                  | Transmission | Manual                     | CO2                       | -            |
| Doors             | 4                  | Gears        | 5                          |                           |              |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 06/05/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                         |   |
|-------------------------|---|
| Manual air-conditioning | ✓ |
| Cruise control          | ✓ |
| Tow                     | ✓ |
| Central locking         | ✓ |
| Electric windows        | ✓ |
| Park Distance Control   | ✓ |
| Audio System            | ✓ |

## Removable element

|                            |   |
|----------------------------|---|
| Spare wheel (wheel & tyre) | ✓ |
|----------------------------|---|

## Technical Document

|             |   |
|-------------|---|
| User manual | ✓ |
| Spare key   | ✓ |
| Remote key  | ✓ |

## Tyres

|                                     |                                                                                     |                                     |                                                                                      |
|-------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|--------------------------------------------------------------------------------------|
| Bridgestone 195/65/15 Summer 3.0 mm |  | Bridgestone 195/65/15 Summer 3.0 mm |  |
| Vredestein 195/65/15 Summer 5.0 mm  |  | Vredestein 195/65/15 Summer 4.0 mm  |  |

## Exterior

|   |                                                                                     |             |                    |   |                                                                                      |             |                    |
|---|-------------------------------------------------------------------------------------|-------------|--------------------|---|--------------------------------------------------------------------------------------|-------------|--------------------|
| 1 |  | Part        | Side panel         | 2 |  | Part        | Door               |
|   |                                                                                     | Position    | Left               |   |                                                                                      | Position    | Back               |
|   |                                                                                     | Damages     | Dented             |   |                                                                                      | Damages     | Dented             |
|   |                                                                                     | Severity    | Diameter (mm) > 20 |   |                                                                                      | Severity    | Diameter (mm) > 20 |
|   |                                                                                     | Repair mode | Smart Repair       |   |                                                                                      | Repair mode | Smart Repair       |

3



|             |             |
|-------------|-------------|
| Part        | Tipper body |
| Position    | -           |
| Damages     | Scratched   |
| Severity    | -           |
| Repair mode | For info    |

● ● ● ● ● ●

4



|             |                    |
|-------------|--------------------|
| Part        | Side panel         |
| Position    | Right              |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

● ●

5



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Right              |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

● ●

7



|             |                  |
|-------------|------------------|
| Part        | Other bodywork   |
| Position    | -                |
| Damages     | Chemical deposit |
| Severity    | -                |
| Repair mode | For info         |

buitenzijde voertuig

● ● ●

### Interior damage


8



|             |             |
|-------------|-------------|
| Part        | Boot carpet |
| Position    | Back        |
| Damages     | Broken      |
| Severity    | -           |
| Repair mode | Replace     |

### Others

6



|             |                  |
|-------------|------------------|
| Part        | Damage appraisal |
| Position    | Front            |
| Damages     | Stone impact     |
| Severity    | -                |
| Repair mode | For info         |