



VOLKSWAGEN T6/MULTIVAN/CARAVELLE

Transporter T6 Kurz EU6



VIN NO WV1ZZZ7HZHH172140
Registration Number HZHH172140

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2023-07-01	1	1	107320 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2017-07-25	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250908092702
Inspection Date / Place	2025-09-08 / BCA Neuss	Cosmetic Grade	9

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	4
Body Type	Box Wagon	Drive Train	Front
Seat Colour		No of Seats	2
Seat Covering Name	anthrazit	Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	153

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

USB Socket	Anti-lock braking	Bluetooth telephone interface	Heated wing mirrors
Remote central locking	Radio	Airbag Status	Auxiliary Socket
Diesel particulate filter	Remote adjusting wing mirrors	Stability control	Rear parking sensors

Equipment Details


Air Conditioning	Yes
------------------	-----

Wheels & Tyres


Right Rear Tyre Depth	8	Left Rear Tyre Depth	8
Right Front Tyre Depth	8	Left Front Tyre Depth	8

Cosmetic Damage

29 Schäden




0 Schäden



Component		Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Hood	Bodywork / Dent / Dent	
3	Hood	Bodywork / Dent / Dent	
4	Hood	Bodywork / Dent / Dent	
5	Corner Bumper / Front Right	Paint / Scratch / Scuff	
6	Door / Front Left	Bodywork / Dent / Dent	
7	Door / Front Left	Bodywork / Dent / Dent	
8	Door / Front Left	Paint / Scratch / Scuff	
9	Door / Front Left	Paint / Scratch / Scuff	
10	Side Panel / Back Left	Paint / Scratch / Scuff	
11	Roof	Bodywork / Dent / Dent	
12	Corner Bumper / Back Left	Paint / Scratch / Scuff	

13	Back Light / Right	Glass Break
14	Corner Bumper / Back Right	Paint / Scratch / Scuff
15	Side Panel / Back Right	Bodywork / Dent / Dent
16	Side Panel / Back Right	Bodywork / Dent / Dent
17	Side Panel / Back Right	Bodywork / Dent / Dent
18	Side Panel / Back Right	Bodywork / Dent / Dent
19	Side Panel / Back Right	Bodywork / Dent / Dent
20	Door / Back Right	Bodywork / Dent / Dent
21	Door / Back Right	Bodywork / Dent / Dent
22	Door / Back Right	Bodywork / Dent / Dent
23	Door / Back Right	Paint / Scratch / Scuff
24	Door / Back Right	Bodywork / Dent / Dent
25	Door / Back Right	Bodywork / Dent / Dent
26	Door / Front Right	Bodywork / Dent / Dent
27	Door / Front Right	Bodywork / Dent / Dent
28	Door / Front Right	Bodywork / Dent / Dent
29	Tailgate	Bodywork / Dent / Dent



1. Hood
Bodywork / Dent / Dent -




2. Hood
Bodywork / Dent / Dent -




3. Hood
Bodywork / Dent / Dent -




4. Hood
Bodywork / Dent / Dent -




5. Corner Bumper / Front Right
Paint / Scratch / Scuff -



6. Door / Front Left
Bodywork / Dent / Dent -



7. Door / Front Left
Bodywork / Dent / Dent -




8. Door / Front Left
Paint / Scratch / Scuff -



9. Door / Front Left
Paint / Scratch / Scuff -



10. Side Panel / Back Left
Paint / Scratch / Scuff -



11. Roof
Bodywork / Dent / Dent -




12. Corner Bumper / Back Left
Paint / Scratch / Scuff -



13. Back Light / Right
Glass Break -



14. Corner Bumper / Back Right
Paint / Scratch / Scuff -



15. Side Panel / Back Right
Bodywork / Dent / Dent -




16. Side Panel / Back Right
Bodywork / Dent / Dent -




17. Side Panel / Back Right
Bodywork / Dent / Dent -




18. Side Panel / Back Right
Bodywork / Dent / Dent -




19. Side Panel / Back Right
Bodywork / Dent / Dent -




20. Door / Back Right
Bodywork / Dent / Dent -




21. Door / Back Right
Bodywork / Dent / Dent -




22. Door / Back Right
Bodywork / Dent / Dent -



23. Door / Back Right
Paint / Scratch / Scuff -



24. Door / Back Right
Bodywork / Dent / Dent -




25. Door / Back Right
Bodywork / Dent / Dent -



26. Door / Front Right
Bodywork / Dent / Dent -



27. Door / Front Right
Bodywork / Dent / Dent -



28. Door / Front Right
Bodywork / Dent / Dent -



29. Tailgate
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓
Parking Sensors / Cameras Functioning	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)