


Vehicle details

VIN	WV1ZZZ7HZ JH207312	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	V4-18-TD	Model	TRANSPORTER 2.0TSI 110kW L2H1 4d	Maintenance mileage	-
Registration date	26/11/2018	Year	2018	Exterior Color	Silver Metallic
Odometer	129 006 km	Engine size	1968	interior Color	Black
Fuel	CNG	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	4	Gears	6		

Inspection Details


Inspection date	06/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element



Technical Document

Spare key	✓
Remote key	✓

Tyres

Michelin 215/65/16 All seasons 4.0 mm			Michelin 215/65/16 All seasons 4.0 mm	
Continental 215/65/16 All seasons 6.0 mm			Continental 215/65/16 All seasons 5.0 mm	

Exterior

3



Part

Door

Position

Left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

4



Part

Tailgate / Boot door

Position

Back

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

●

●

5



Part

Tipper body

Position

Back

Damages

Scratched

Severity

-

Repair mode

For info

●

●

●

●

6



Part

Door

Position

Right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

●

8



Part

Roof

Position

-

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

●

●

●

●

●

Interior damage

1



Part	Fabric seat
Position	Front left
Damages	Cut
Severity	-
Repair mode	For info

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

7



Part	Damage appraisal
Position	Front
Damages	Stone impact
Severity	-
Repair mode	For info