

VIN	WV1ZZZ7HZ KX001423	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	V8-67-TV	Model	TRANSPORTER 2.0TSI 150kW 7-DSG L1H1 4d	Maintenance mileage	-
Registration date	09/07/2019	Year	2019	Exterior Color	Silver Metallic
Odometer	187 633 km	Engine size	1968	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection date	09/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------

Inspection date	09/10/2025
-----------------	------------

Inspection loc.	Dekra Ayvens
-----------------	--------------



Manual air-conditioning	✓
Cruise control	✓
Automatic Gearbox	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

100

User manual	
Spare key	
Remote key	

Bridgestone 215/60/17 Summer 4.0 mm

Continental 215/60/17 Summer 7.0 mm

Bridgestone 215/60/17 Summer 4.0 mm

Exterior

3		Part Position Damages Severity Repair mode	Fuel filler flap Front left Dent & Chips Diameter (mm) > 20 Repair	4		Part Position Damages Severity Repair mode	Door Left Dented Diameter (mm) > 20 Repair
5		Part Position Damages Severity Repair mode	Tailgate / Boot door Back Dented Diameter (mm) > 20 Repair	6		Part Position Damages Severity Repair mode	Door Right Dented Diameter (mm) > 20 Repair
7		Part Position Damages Severity Repair mode	Wing Front right Dented Diameter (mm) > 20 Smart Repair	8		Part Position Damages Severity Repair mode	Exterior door mirror shell Front right Scratched - Repair
9		Part Position Damages Severity Repair mode	Bumper Front Scratched - Repair	10		Part Position Damages Severity Repair mode	Windscreen - Stone impact - For info
11		Part Position Damages Severity Repair mode	Roof - Chemical deposit - Lumpsum repair	12		Part Position Damages Severity Repair mode	Other bodywork - Chemical deposit - For info buitenzijde voertuig
13		Part Position Damages Severity Repair mode	Tipper body - Scratched - For info				

Interior damage

1		Part Position Damages Severity Repair mode	Interior cleaning Front right Stained/dirty - Cleaning
---	---	--	--

2



●●

Part	Steering wheel
Position	Front left
Damages	Not conform
Severity	-
Repair mode	For info

14



●●

Part	Interior tailgate lining
Position	-
Damages	Not conform
Severity	-
Repair mode	For info