

Inspection Protocol

TRADING
SOLUTIONS

VW TRANSPORTER T32 2.0 TDI BMT

Vehicle information

License plate	WYO667	Inspected by	C.C.
Year model	2021	Date of inspection	2025-03-13
Manuf. year/month	2020-09	City	Björkvik
First day in traffic	2020-09	Keys	3
Colour	Vit	Service book	Elektronisk servicebok
Mileage	141 510 km	Latest service	-
Fuel	Diesel	Mileage at the latest service -	
Transmission	DSG Sekventiell	Summer tires	16" plåtfälg 5/5/7/7
Engine effect	110 kW	Winter tires	plåtfälg dubbat 3/3/3/3

Damages

Location	Damage	Comments	Costs excluding VAT
Door, Lef side mirror	Scratches 30-100 mm		100 €
Wing, Rear left	Scratches below 30 mm		70 €
Wing, Rear left	Fine scratches		-
Boot lid, Right transport door	Scratches above 100 mm		230 €
Boot lid, Left transport door	Dents below 30 mm		70 €
Wing, Rear right	Paint retouch traces		10 €
Sills, Right	Paint retouch traces		10 €
Door, Right sliding door	Paint damages		-
Door, Righ side mirror	Scratches below 30 mm		70 €
Bumper, Front	Cracks large above 100 mm		410 €

Total excl. VAT	970 €
-----------------	-------

Comments

Förlängd garanti och serviceavtal på 5 år/15.000 mil måste överlåtas från kund till köpare giltig till 2026-03-31

Images

[See all images in large format](#)
























Dörr Vänster backspegel Repor 3-10 cm 1 100 kr




Skärm Vänster bak Repor under 3 cm 800 kr



Skärm Vänster bak Polerbara repor



Bagagelucka Höger transportdörr Repor över 10 cm 2 500 kr



Bagagelucka Vänster transportdörr Bucklor under 3 cm 800 kr



Skärm Höger bak Lackbättring 50 kr



Trösklar Höger Lackbättring 50 kr



Dörr Höger skjutdörr Lackskador



Dörr Höger backspegel Repor under 3 cm 800 kr



Stötfångare Fram Sprickor, stora över 10 cm 4 500 kr







