



VOLKSWAGEN Caddy 3
Caddy 1.4

VIN NO WV2ZZZ2KZ6X114467
Registration Number KZ6X114467



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-01-01	3	2	240252 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2006-05-31	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251006133017
Inspection Date / Place	2025-10-06 / SULOJA Brackel	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Blue	Engine Size (cc)	1390
Engine Size	1.4	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Art Grey	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	199
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			





Equipment

Tow ball	Airbag Status	Front fog lamps	Remote adjusting wing mirrors
Split folding rear seats	Radio	Trip Computer	Anti-lock braking
Heated wing mirrors	Remote central locking	Stability control	


Equipment Details

Tow Ball Type	Static	Air Conditioning	No
Seat Heating	No		


Wheels & Tyres

Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

31 Schäden



5 Schäden




5/15 - Report Number P20251006133017

13	Door / Back Left	Paint / Corrosion
14	Door / Back Left	Paint / Scratch / Scuff
15	Side Panel / Back Left	Bodywork / Dent / Dent
16	Side Panel / Back Left	Paint / Scratch / Scuff
17	Side Panel / Back Left	Paint / Scratch / Scuff
18	Bumper / Back	Paint / Scratch / Scuff
19	Tailgate	Bodywork / Dent / Dent
20	Tailgate	Paint / Scratch / Scuff
21	Side Panel / Back Right	Bodywork / Dent / Dent
22	Bumper trim	Paint / Scratch / Scuff
23	Side Panel / Back Right	Paint / Scratch / Scuff
24	Door / Back Right	Paint / Scratch / Scuff
25	Door / Front Right	Paint / Corrosion
26	Door / Front Right	Paint / Corrosion
27	Door / Front Right	Paint / Scratch / Scuff
28	Door / Front Right	Paint / Scratch / Scuff
29	Fender / Front Right	Paint / Corrosion
30	Rocker Panel / Center Right	Paint / Corrosion
31	Panel Filling / Front Right	Interior / Scratched
32	Panel Filling / Back Right	Interior / Non - compliant
33	Hubcap / Back Left	Out of Bodywork / Breakage
34	Seat / Front Left	Interior / Holed
35	Panel Filling / Front Left	Interior / Scratched
36	Dashboard / Front	Interior / Scratched
37	Roof	Paint / Scratch / Scuff



1. Hood
Bodywork / Dent / Dent -



2. Hood
Paint / Scratch / Scuff -



3. Bumper / Front
Paint / Scratch / Scuff -



4. Bumper / Front
Paint / Scratch / Scuff -



5. Fender / Front Left
Bodywork / Dent / Dent -



6. Fender / Front Left
Bodywork / Dent / Dent -



7. Fender / Front Left
Paint / Corrosion -




8. Fender / Front Left
Paint / Corrosion -



9. Door / Front Left
Bodywork / Dent / Dent -



10. Door / Front Left
Paint / Scratch / Scuff -



11. Door / Front Left
Paint / Corrosion -



12. Rocker Panel / Center Left
Paint / Corrosion -



13. Door / Back Left
Paint / Corrosion -



14. Door / Back Left
Paint / Scratch / Scuff -



15. Side Panel / Back Left
Bodywork / Dent / Dent -



16. Side Panel / Back Left
Paint / Scratch / Scuff -




17. Side Panel / Back Left
Paint / Scratch / Scuff -



18. Bumper / Back
Paint / Scratch / Scuff -



19. Tailgate
Bodywork / Dent / Dent -



20. Tailgate
Paint / Scratch / Scuff -



21. Side Panel / Back Right
Bodywork / Dent / Dent -



22. Bumper trim
Paint / Scratch / Scuff -



23. Side Panel / Back Right
Paint / Scratch / Scuff -



24. Door / Back Right
Paint / Scratch / Scuff -



25. Door / Front Right
Paint / Corrosion -



26. Door / Front Right
Paint / Corrosion -



27. Door / Front Right
Paint / Scratch / Scuff -



28. Door / Front Right
Paint / Scratch / Scuff -




29. Fender / Front Right
Paint / Corrosion -



30. Rocker Panel / Center Right
Paint / Corrosion -



31. Panel Filling / Front Right Interior / Scratched -



32. Panel Filling / Back Right Interior / Non-compliant -



33. Hubcap / Back Left Out of Bodywork / Breakage -



34. Seat / Front Left Interior / Holed -



35. Panel Filling / Front Left Interior / Scratched -



36. Dashboard / Front Interior / Scratched -



37. Roof
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	!	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)