



Volkswagen Caddy (Segm. B1): 1UXY609

Vinnnumber:	WV2ZZZ2KZJX147573	Versionname:	Caddy Maxi Trendline 2.0TDi BMT 102pk/cv 4p 5pl (dub cab)
First Registrationdate:	30/08/2018	Fiscalpower:	
Expertise Mileage:	213137	Power Kw:	75
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:			
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Battery functioning	Yes		
Registration Certificate Car (BE)	Yes		
Maintenance	NOT OK		

Options

Type of Maintenance book	Digital maintenance	Type of Tow bar	Tow bar fixed
Type of GPS storage	N.A.		
Number of keys total	2		

Tyres

Tyre size RL	205/55 R 16 94 H
Tyre type FL	Winter
Tyre type RL	Winter
Tyre profile depth FR	3.0
Tyre profile depth RR	4.0
Tyre size FR	205/55 R 16 94 H
Tyre make FR	259

205/55/16/94 H			
Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Tyre size RR	205/55 R 16 94 H
Tyre make RR	259
Tyre profile depth FL	3.0
Tyre size FL	205/55 R 16 94 H
Tyre make FL	259
Tyre profile depth RL	4.0
Tyre type FR	Winter
Tyre type RR	Winter
Tyre make RL	259

Assistance equipment

Number of charging cables (normal)	0	Jack	Yes
Spare wheel	Yes		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Check



Dashboard, Hole, Smart repair



Door panel FL, Stain, Cleaning



Door panel FR, Stain, Cleaning



Interior, Worn, Acceptable



Seat cover FL, Strained, Acceptable



Windscreen, Tear, Replace



Headlight L, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable



Bonnet, Stone chip(s), Acceptable





Wheel cover FL, Scratch(es), Acceptable



Wing FL, Dent(s), Paintless dent repair



Door RL, Scratch(es), Acceptable



Boot carpet, Damaged, Acceptable



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Rear light L, Broken, Replace



Bumper R, Scratch(es), Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Spot repair



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Outside rear-view mirror cover R (upper), Scratch(es), Acceptable



Wing FR, Dent(s), Repair and paint (complete)





Wheel cover FR, Scratch(es), Replace



Bodywork, Not original part, Remove lettering

