

Inspection Protocol

VOLKSWAGEN FINANCIAL SERVICES
FINANSIERING. FÖRSÄKRING. MOBILITET.

VW CADDY MAXI LIFE 7-SEATER 2.0 TDI BMT 4MOTION

Vehicle information

License plate	JDP00G	Inspected by	T.H.
Year model	2019	Date of inspection	2025-04-11
Manuf. year/month	2019-03	City	Björkvik
First day in traffic	2019-03	Keys	1
Colour	Vit	Service book	Elektronisk servicebok
Mileage	225 990 km	Latest service	-
Fuel	Diesel	Mileage at the latest service	-
Transmission	DSG Sekventiell	Summer tires	17" alu-fälg 3/3/3/3
Engine effect	110 kW	Winter tires	saknas

Damages

Location	Damage	Comments	Costs excluding VAT
Missing	Nyckel inkl. kodning		300 €
Felsökning	varningslampa		280 €
Other	Other	Missljud från svänghjul	-
Rear bumpers	Normalt slitage	Lastrepor	-
Windshield	byte		1 090 €
Recond, Cleaning	Backseat		170 €
Recond, Cleaning	1 säte		60 €
Recond, Cleaning	1 säte	Smutsig interiör	60 €
Interiör	Worn steering wheel		180 €
Total excl. VAT			2 140 €

Service occasions

Fordonet ska tvättas

Images

[See all images in large format](#)



















