



Volkswagen Transporter: 2AHK369

Vinnumber:	WV2ZZZ7HZMH094537	Versionname:	Transporter Combi LWB 2.0TDi 110pk/cv 9pl.
First Registrationdate:	6/04/2021	Fiscalpower:	
Expertise Mileage:	178559	Power Kw:	81
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:			
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

215/65/16/107 T				
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/65 R 16 107 T
Tyre size FR				215/65 R 16 107 W
Tyre size RL				215/65 R 16 107 T
Tyre size RR				215/65 R 16 107 W
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Damaged, Acceptable



Interior, Dirty, Forfeit



Bonnet, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Smart repair



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door FL, Scratch(es), Spot repair



Door RL, Scratch(es), Spot repair



Tailgate / Boot, Dent(s) and scratch(es), Replace and paint



Bumper R, Scratch(es), Smart repair



Internal boot lining L, Scratch(es), Replace



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Wheel cover RR, Scratch(es), Acceptable



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Bodywork, Not original part, Remove lettering

