



VOLKSWAGEN T6/MULTIVAN/CARAVELLE

Transporter T6.1 DSG Kurz



VIN NO WV2ZZZ7HZN015294
Registration Number HZN015294

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-02-01	1	2	139558 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-04-07	123920	2022-02-11	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250902090829
Inspection Date / Place	2025-09-02 / BCA Neuss	Cosmetic Grade	3


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Unknown
Colour	Black	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	4
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	3
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Airbag Status	Bluetooth telephone interface	Diesel particulate filter
Front parking sensors	Heated wing mirrors	Remote central locking	Satellite navigation
Electrically folding wing mirrors	Radio	Tow ball	Anti-lock braking
Cruise control	Digital Radio	Heated windscreen	Remote adjusting wing mirrors
Reversing Camera	Stability control	Leather steering wheel	Rear parking sensors

Equipment Details


Tow Ball Type	Static	Air Conditioning	Yes
Extra Wheel / Tyre Set	Winter Tyres - Steel	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

Cosmetic Damage

11 Schäden



1 Schäden




Component		Damage	Comments
1	Hood	Paint / Stone Chip	
2	Hood	Bodywork / Dent / Dent	
3	Door / Front Left	Bodywork / Dent / Dent	
4	Side Panel / Back Left	Paint / Scratch / Scuff	
5	Tailgate	Paint / Scratch / Scuff	
6	Side Panel / Back Right	Bodywork / Dent / Dent	
7	Side Panel / Back Right	Bodywork / Dent / Dent	
8	Side Panel / Back Right	Paint / Scratch / Scuff	
9	Door / Back Right	Bodywork / Dent / Dent	
10	Roof	Bodywork / Dent / Dent	
11	Roof	Bodywork / Dent / Dent	
12	Steering Wheel / Front	Interior / Scraped	



1. Hood
Paint / Stone Chip -



2. Hood
Bodywork / Dent / Dent -



3. Door / Front Left
Bodywork / Dent / Dent -



4. Side Panel / Back Left
Paint / Scratch / Scuff -



5. Tailgate
Paint / Scratch / Scuff -



6. Side Panel / Back Right
Bodywork / Dent / Dent -



7. Side Panel / Back Right
Bodywork / Dent / Dent -



8. Side Panel / Back Right
Paint / Scratch / Scuff -



9. Door / Back Right
Bodywork / Dent / Dent -



10. Roof
Bodywork / Dent / Dent -



11. Roof
Bodywork / Dent / Dent -



12. Steering Wheel / Front
Interior / Scraped -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	!
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Engine

Engine Status / EML	!	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	!
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)