



Volkswagen Caddy: 2BEC124

Vinnumber:	WV2ZZZSKZNX014224	Versionname:	Caddy Maxi Life 1.5TSi 114pk/cv DSG7
First Registrationdate:	19/10/2021	Fiscalpower:	
Expertise Mileage:	123020	Power Kw:	84
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	25700 km - 647 dagen		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	1	Luggage cover	
Type of Maintenance book	Digital maintenance	Type of Tow bar	Tow bar fixed
Type of GPS storage	N.A.		


Tyres

	215/55/17/98 W			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				215/55 R 17 98 W
Tyre size FR				215/55 R 17 98 W
Tyre size RL				215/55 R 17 98 W
Tyre size RR				215/55 R 17 98 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Registration document, Missing, Replace



Certificate Of Conformity, Missing, Replace



Ignition key, Missing, Replace



Instrument panel, complete, Not original part, Check



Centre console, Scratch(es), Acceptable



Bumper F, Scratch(es), Spot repair



Windscreen, Stone chip(s), Replace



Alloy rim FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Acceptable





Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Acceptable



Wing RR, Dent(s), Acceptable



Sliding door R, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Step R, Dent(s), Acceptable



Roof pillar R, Scratch(es), Acceptable



