



VOLKSWAGEN Touran

Touran 1.4 TSI DSG

VIN NO WVGZZZ1TZCW111394
Registration Number TZCW111394



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-03-01	2	1	223660 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-03-14	215783	2012-09-19	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250912140914
Inspection Date / Place	2025-09-12 / BCA Heidenheim	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1390
Engine Size	1.4	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	154
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Bi Xenon Headlamps
Front fog lamps	Headlamp wash/wipe	Remote adjusting wing mirrors	Reversing Camera
Satellite navigation	Stability control	CD Player	Radio
Trip Computer	Alloys wheels	Auxiliary Socket	Cruise control
Front parking sensors	Heated wing mirrors	Remote central locking	Roof rails
Split folding rear seats	Sunroof	Leather steering wheel	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
Seat Heating	Front	Sunroof Type	Opening Panoramic

Wheels & Tyres


Left Front Tyre Depth	8	Right Front Tyre Depth	8
Right Rear Tyre Depth	7	Left Rear Tyre Depth	6

Cosmetic Damage

24 Schäden



5 Schäden



Component		Damage	Comments
1	Seat / Front Left	Interior / Worn - out	
2	Panel Filling / Back Left	Interior / Holed	
3	Tailgate Upholstery / Back	Interior / Scratched	
4	Tailgate Upholstery / Back	Interior / Scratched	
5	Panel Filling / Front Right	Interior / Worn - out	
6	Windshield / Front	Glass Break / Impact	
7	Windshield / Front	Glass Break / Impact	
8	Door / Back Right	Paint / Poor Previous Repair	
9	Side Panel / Back Left	Paint / Poor Previous Repair	
10	Fender / Front Left	Bodywork / Dent / Dent	
11	Bumper / Front	Paint / Scratch / Scuff	
12	Hood	Paint / Scratch / Scuff	

13	Fender / Front Right	Bodywork / Dent / Dent
14	Fender / Front Right	Bodywork / Dent / Dent
15	Fender / Front Right	Bodywork / Dent / Dent
16	Fender / Front Right	Bodywork / Dent / Dent
17	Fender / Front Right	Bodywork / Dent / Dent
18	Rim / Back Right	Out of Bodywork / Scratch
19	Bumper / Back	Bodywork / Dent / Dent
20	Bumper / Back	Paint / Scratch / Scuff
21	Side Panel / Back Left	Bodywork / Dent / Dent
22	Side Panel / Back Left	Bodywork / Dent / Dent
23	Door / Back Left	Bodywork / Dent / Dent
24	Door / Back Left	Bodywork / Dent / Dent
25	Door / Back Left	Bodywork / Dent / Dent
26	Pillar / Back Left	Bodywork / Dent / Dent
27	Door / Front Left	Paint / Corrosion
28	Door / Front Left	Bodywork / Dent / Dent
29	Roof	Bodywork / Dent / Dent



1. Seat / Front Left
Interior / Worn - out -



2. Panel Filling / Back Left
Interior / Holed -




3. Tailgate Upholstery / Back
Interior / Scratched -



4. Tailgate Upholstery / Back
Interior / Scratched -



5. Panel Filling / Front Right
Interior / Worn - out -



6. Windshield / Front
Glass Break / Impact -




7. Windshield / Front
Glass Break / Impact -



8. Door / Back Right
Paint / Poor Previous Repair -




9. Side Panel / Back Left
Paint / Poor Previous Repair -




10. Fender / Front Left
Bodywork / Dent / Dent -




11. Bumper / Front
Paint / Scratch / Scuff -




12. Hood
Paint / Scratch / Scuff -




13. Fender / Front Right
Bodywork / Dent / Dent -




14. Fender / Front Right
Bodywork / Dent / Dent -



15. Fender / Front Right
Bodywork / Dent / Dent -



16. Fender / Front Right
Bodywork / Dent / Dent -



17. Fender / Front Right
Bodywork / Dent / Dent -




18. Rim / Back Right
Out of Bodywork / Scratch -




19. Bumper / Back
Bodywork / Dent / Dent -




20. Bumper / Back
Paint / Scratch / Scuff -




21. Side Panel / Back Left
Bodywork / Dent / Dent -




22. Side Panel / Back Left
Bodywork / Dent / Dent -



23. Door / Back Left
Bodywork / Dent / Dent -



24. Door / Back Left
Bodywork / Dent / Dent -




25. Door / Back Left
Bodywork / Dent / Dent -




26. Pillar / Back Left
Bodywork / Dent / Dent -



27. Door / Front Left
Paint / Corrosion -



28. Door / Front Left
Bodywork / Dent / Dent -



29. Roof
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)