



VOLKSWAGEN Touran

Touran 1.2 TSI BlueMotion Technology



VIN NO WVGZZZ1TZFW035876
Registration Number TZFW035876

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-05-01	3	2	129309 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2014-11-27	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250909115005
Inspection Date / Place	2025-09-09 / BCA Neuss	Cosmetic Grade	3

Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Silver	Engine Size (cc)	1197
Engine Size	1.2	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	anthrazit	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	139

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Alloys wheels	Auxiliary Socket	Cruise control
Front parking sensors	Remote adjusting wing mirrors	Roof rails	Stability control
Leather steering wheel	Rear parking sensors	Airbag Status	Anti-lock braking
Bluetooth telephone interface	Front fog lamps	Heated wing mirrors	Remote central locking
Satellite navigation	CD Player	Radio	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

11 Schäden



1 Schäden




Component		Damage	Comments
1	Seat / Front Left	Interior / Scratched	
2	Pillar / Back Left	Bodywork / Dent / Dent	
3	Pillar / Back Right	Paint / Scratch / Scuff	
4	Windshield / Front	Paint / Chipping	
5	Corner Bumper / Front Right	Paint / Scratch / Scuff	
6	Bumper / Front	Paint / Scratch / Scuff	
7	Corner Bumper / Front Left	Paint / Scratch / Scuff	
8	Rim / Front Left	Out of Bodywork / Scratch	
9	Fender / Back Left	Bodywork / Dent / Dent	
10	Roof	Bodywork / Dent / Dent	
11	Corner Bumper / Back Left	Paint / Scratch / Scuff	
12	Door / Front Right	Paint / Scratch / Scuff	




1. Seat / Front Left
Interior / Scratched -



2. Pillar / Back Left
Bodywork / Dent / Dent -



3. Pillar / Back Right
Paint / Scratch / Scuff -



4. Windshield / Front
Paint / Chipping -



5. Corner Bumper / Front Right
Paint / Scratch / Scuff -




6. Bumper / Front
Paint / Scratch / Scuff -




7. Corner Bumper / Front Left
Paint / Scratch / Scuff -



8. Rim / Front Left
Out of Bodywork / Scratch -



9. Fender / Back Left
Bodywork / Dent / Dent -



10. Roof
Bodywork / Dent / Dent -



11. Corner Bumper / Back Left
Paint / Scratch / Scuff -



12. Door / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Clutch

Clutch Functioning

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)