



VOLKSWAGEN TOURAN: 1WGU329

Vinnnumber:	WVGZZZ1TZKW062205	Versionname:	1.6 TDi Trendline DSG
First Registrationdate:	3/06/2019	Fiscalpower:	
Expertise Mileage:	125436	Power Kw:	85
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Steel
Transmission:		Parking lot:	3502
Fueltype:	Diesel		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting Halogen		
Type of GPS:	No GPS		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Tyres

	205/60/16/96 V			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/60 R 16 96 V
Tyre size FR				205/60 R 16 96 V
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	122,52
Bonnet, Dent(s) and scratch(es), Acceptable	0,00



Door FL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), Replace

0,00




Wheel cover FR, Deformed / Strained, Replace

61,26



Wheel cover RR, Scratch(es), Replace

61,26



Wing RR, Scratch(es), Acceptable

0,00

