



VOLKSWAGEN TOURAN: 1WMZ682

Vinnumber:	WVGZZZ1TZKW990495	Versionname:	1.6 TDi Trendline DSG
First Registrationdate:	17/07/2019	Fiscalpower:	
Expertise Mileage:	122652	Power Kw:	85
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2709
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	SD present		

Limited Technical Inspection

Degree of wear

205/60/16/96 H				
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	4298,58
Interior, Dirty, Cleaning	170,61



Air vent RM, Broken, Replace

173,18



Roof liner, Tear, Replace

866,36



Roof liner, Tear, Forfeit

208,00



Headrest RR, Not original part, Check

0,00



Bumper F, Scratch(es), Spot repair

144,58



Windscreen, Bad repair, Replace

728,32



Wing RL, Dent(s), Repair and paint (complete)

478,65



Alloy rim FL, Scratch(es), Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Step L, Scratch(es), Acceptable

0,00



Boot lid covering R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Tailgate / Boot, Dent(s), Paintless dent repair

124,08



Door RR, Dent(s) and scratch(es), Repair and paint (complete)

550,50



Wing RR, Scratch(es), Repair and paint (complete)

420,65



Alloy rim FR, Scratch(es), Acceptable

0,00



Wing FR, Scratch(es), Acceptable

0,00



Central pillar R, Dent(s) and scratch(es), Spot repair

144,58



Alloy rim RR, Scratch(es), Acceptable

0,00



Tyre RR, Worn, Acceptable

0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00

