


Vehicle details

VIN	WVGZZZ1TZ LW030543	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	H4-48-GD	Model	TOURAN 1.5 TSI DSG 110kW Comfortline Business 5d	Maintenance mileage	-
Registration date	22/01/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	252 557 km	Engine size	1498	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	07/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
7 seater	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element


Load cover	✓
------------	---

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 205/60/16 Summer 3.0 mm



Pirelli 205/60/16 Summer 3.0 mm



Michelin 205/60/16 Summer 5.0 mm

Michelin 205/60/16 Summer 5.0 mm

Exterior

1



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

2



Part	Step plate
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

5



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Tailgate / Boot door
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



Part	Wing
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

9



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

10



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

Interior damage

3



Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

4



Part	Fabric seat
Position	Centre
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

7



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Smart Repair