



Volkswagen Touran (UKL): 2BAZ678

Vinnumber:	WVGZZZ1TZW039109	Versionname:	Touran Highline 2.0TDi 150pk/cv 5p DSG7
First Registrationdate:	15/09/2021	Fiscalpower:	
Expertise Mileage:	100532	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/60/16/96 V				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/60 R 16 96 V
Tyre size FR				205/60 R 16 96 V
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Air vent RM, Broken, Replace



Bumper F, Scratch(es), Spot repair



Alloy rim FL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Spot repair



Wheel aperture RR, Dent(s) and scratch(es), Spot repair



Rear window, Not original part, Check




Alloy rim RR, Scratch(es), Acceptable



Tyre RR, Tear, Replace



Step R, Dent(s), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Door window RR, Not original part, Check

