



VOLKSWAGEN TOURAN: GD-438-QJ

Vinnumber:	WVGZZZ1TZNW002314	Versionname:	
First Registrationdate:	17/12/2021	Fiscalpower:	
Expertise Mileage:	117351	Power Kw:	
Bodytype:	MPV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Dark Grey
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Dark Grey
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Luggage cover
Number keys remote	1	Roof bar black
GPS big screen color		Rear view camera

Degree of wear

	205/60/16/96 V			
Summer tyres:	Fr.L.	Continental: 80%	Fr.R.	Pirelli: 30%
	Re.L.	Continental: 30%	Re.R.	Continental: 60%
Tyre profile depth FL				2.9
Tyre profile depth FR				6.3
Tyre profile depth RL				6.2
Tyre profile depth RR				4.4
Tyre size FL				205/60 R 16 96 V
Tyre size FR				205/60 R 16 96 V
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				All seasons
Tyre type FR				Summer
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				256
Tyre make FR				264
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel	Yes	Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)			



Interior, Dirty, Chemical cleaning



Tyres, No damage, Acceptable



Tyre FL, Out of tolerance, Replace



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace



Wing RL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Paint



Wing FR, Scratch(es), Paint



Bumper R, Deformed / Strained, Repair and paint (complete)



Boot lid covering R, Scratch(es), Repair/replace (lump sum)

