



VOLKSWAGEN Tiguan

Tiguan 2.0 TDI DPF BlueMotion Technology



VIN NO WVGZZZ5NZFW105109
Registration Number NZFW105109

MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	2	1	236262 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-10-29	213475	2015-07-31	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250910092347
Inspection Date / Place	2025-09-10 / BCA Neuss	Cosmetic Grade	4

Vehicle Summary




Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	138
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Alloys wheels	Bluetooth telephone interface	Diesel particulate filter
Heated wing mirrors	Remote central locking	Satellite navigation	CD Player
Leather steering wheel	Rear parking sensors	Airbag Status	Anti-lock braking
Cruise control	Front parking sensors	Remote adjusting wing mirrors	Roof rails
Stability control	Electrically folding wing mirrors	Radio	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	1	Left Front Tyre Depth	1
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage


7 Schäden



0 Schäden




Component		Damage	Comments
1	Windshield / Front	Glass Break / Impact	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Door / Back Left	Bodywork / Dent / Dent	
4	Bumper / Back	Paint / Scratch / Scuff	
5	Door / Back Right	Bodywork / Dent / Dent	
6	Door / Front Right	Bodywork / Dent / Dent	
7	Door / Front Right	Paint / Scratch / Scuff	



1. Windshield / Front
Glass Break / Impact -




2. Bumper / Front
Paint / Scratch / Scuff -



3. Door / Back Left
Bodywork / Dent / Dent -



4. Bumper / Back
Paint / Scratch / Scuff -



5. Door / Back Right
Bodywork / Dent / Dent -



6. Door / Front Right
Bodywork / Dent / Dent -



7. Door / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	!	Tire Pressure Monitoring System	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Clutch			
Clutch Functioning		✔	
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)