



VOLKSWAGEN Tiguan

Tiguan 2.0 TDI SCR 4Motion (BlueMotion Techn.) DSG

VIN NO WVGZZZ5NZJW898094
Registration Number NZJW898094



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-08-01	2	2	95439 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2018-11-07	Germany

Inspection Report Summary


Customer	BCA Online	Report Number	P20250930120117
Inspection Date / Place	2025-09-30 / BCA Oberndorf	Cosmetic Grade	3


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	White	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	167
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Trafficsignrecognition	Airbag Status	Anti-lock braking
Blindspotassist	Cruise control	Fatiguewarningsystem	Front parking sensors
Heated wing mirrors	Remote central locking	Roof rails	Split folding rear seats
Central locking	Electrically adjustable seats	Electrictailgate	Laneassist
LED Headlamps	Rear parking sensors	Tow ball	USB Socket
Alloys wheels	Auxiliary Socket	Bluetooth telephone interface	Diesel particulate filter
Front fog lamps	Head up Display	Remote adjusting wing mirrors	Reversing Camera
Satellite navigation	Stability control	Distancewarningsystem	Electrically folding wing mirrors
Emergencybrakeassist	Leather steering wheel	Radio	


Equipment Details

Tow Ball Type	Pivoted	Air Conditioning	Three Zone Climate Control
Alloy Wheel Size	18	Seat Heating	Front


Wheels & Tyres

Right Front Tyre Depth	2	Left Front Tyre Depth	2
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage



Component	Damage	Comments
1 Other	Anomalyon Element	
2 Bumper / Front	Paint / Scratch / Scuff	
3 Seat Cushion / Front Left	Interior / Ripped	
4 Door / Back Left	Bodywork / Dent / Dent	
5 Door Edge / Back Left	Bodywork / Dent / Dent	
6 Bumper / Back	Paint / Scratch / Line	
7 Tailgate	Paint / Scratch / Line	
8 Fender / Back Right	Paint / Scratch / Line	
9 Spoiler / Back	Paint / Scratch / Line	




1.
Anomalyon Element -



2. Bumper / Front
Paint / Scratch / Scuff -



3. Seat Cushion / Front Left
Interior / Ripped -




4. Door / Back Left
Bodywork / Dent / Dent -




5. Door Edge / Back Left
Bodywork / Dent / Dent -



6. Bumper / Back
Paint / Scratch / Line -



7. Tailgate
Paint / Scratch / Line -



8. Fender / Back Right
Paint / Scratch / Line -



9. Spoiler / Back
Paint / Scratch / Line -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		Not Performed	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)