



Volkswagen Tiguan (KKL): 1VXU250

Vinnnumber:	WVGZZZ5NZKM094872	Versionname:	Tiguan Allspace Comfortline 1.5TSi 150pk/cv 5p
First Registrationdate:	1/04/2019	Fiscalpower:	
Expertise Mileage:	149256	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	SD present		

Tyres

215/65/17/99 H				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/65 R 17 99 H
Tyre size FR				215/65 R 17 99 H
Tyre size RL				215/65 R 17 99 H
Tyre size RR				215/65 R 17 99 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FR, Stain, Acceptable



Bumper F, Scratch(es), Acceptable



Bumper spoiler F, Scratch(es), Smart repair



Door FL, Dent(s), Paintless dent repair



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Step L, Dent(s), Paintless dent repair



Tailgate / Boot, Dent(s), Paintless dent repair



Bumper R, Scratch(es), Acceptable



Outside rear-view mirror base R, Broken, Replace



Mirror side repeater R, Broken, Replace

mirror side repeater R, Broken, Replace



Outside rear-view mirror housing R, Broken, Replace and paint



Door FR, Dent(s), Acceptable



Wing trim FR, Scratch(es), Smart repair

