



VOLKSWAGEN TIGUAN ALLSPACE: 1WQQ905

Vinnnumber:	WVGZZZ5NZKM165710	Versionname:	2.0 TDI SCR Comfortline
First Registrationdate:	13/08/2019	Fiscalpower:	
Expertise Mileage:	123080	Power Kw:	110
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1621
Fueltype:	Diesel		
Maintenance:	OK		
Maintenance:	in 2500 km		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Sun Roof electric:	
Steering wheel multifunctional:		Panoramic roof:	
Seats F heated:		Luggage cover:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	Headlighting Halogen	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	Tow bar collapsible
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	SD present		

Limited Technical Inspection

Degree of wear

235/50/19/103 V				
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1811,00
Headrest RR, Stain, Check:	0,00



Roof liner, Stain, Acceptable

0,00



Door panel RL, Scratch(es), Acceptable

0,00



Door panel RR, Scratch(es), Smart repair

113,74



Door panel FR, Scratch(es), Acceptable

0,00



Glove box, Scratch(es), Acceptable

0,00



Ignition key, Not functioning (well), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Wing FL, Scratch(es), Acceptable

0,00



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)

157,71



Door FL, Dent(s), Acceptable

0,00



Door RL, Dent(s), Paintless dent repair

124,08



Wing RL, Scratch(es), Acceptable

0,00



Alloy rim RL, Scratch(es), Repair and paint (complete)

129,66



Boot carpet, Stain, Acceptable

0,00



Boot lid covering R, Scratch(es), Acceptable

0,00



Boot lid covering R, Dirty, Cleaning

28,43



Bumper R, Scratch(es), Acceptable

0,00



Bumper moulding R, Dent(s) and scratch(es), Replace

331,50



Tailgate / Boot, Dent(s), Acceptable

0,00



Wheel aperture RL, Dent(s) and scratch(es), Spot repair

144,58



Wheel aperture RR, Dent(s) and scratch(es), Acceptable

0,00



Bumper moulding R, Scratch(es), Acceptable

0,00



Alloy rim RR, Scratch(es), Acceptable

0,00



Door RR, Scratch(es), Repair and paint (complete)

434,50



Door trim RR, Scratch(es), Acceptable

0,00



Door FR, Dent(s), Paintless dent repair

93,06



Door FR, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

129,66



Roof, Dent(s), Paintless dent repair

124,08

