


## Vehicle details

|                   |                    |              |                                                    |                           |             |
|-------------------|--------------------|--------------|----------------------------------------------------|---------------------------|-------------|
| VIN               | WVGZZZ5NZ LM002409 | Brand        | VOLKSWAGEN                                         | Maintenance date          | -           |
| Licence Plate     | G3-61-HG           | Model        | Tiguan Allspace 1.5 TSI DSG Comfortline Business 5 | Maintenance mileage       | -           |
| Registration date | 24/10/2019         | Year         | 2019                                               | Exterior Color            | White Solid |
| Odometer          | 107 605 km         | Engine size  | 1498                                               | interior Color            | Grey        |
| Fuel              | Petrol             | Body Type    | -                                                  | Next technical inspection | -           |
| Seats             | -                  | Transmission | Automatic                                          | CO2                       | -           |
| Doors             | 5                  | Gears        | -                                                  |                           |             |

## Inspection Details

|                                                                                     |                                                                                     |                                                                                     |                                                                                    |                                                                                      |                                                                                      |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Inspection date                                                                     | 11/03/2025                                                                          | Inspection loc.                                                                     | Dekra Ayvens                                                                       |                                                                                      |                                                                                      |
|    |    |    |   |   |   |
|   |   |   |  |  |  |
|  |  |  |                                                                                    |                                                                                      |                                                                                      |

## Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| GPS system                 | ✓ |
| Sliding roof               | ✓ |
| Panoramic roof             | ✓ |
| Alloy wheel rims           | ✓ |
| Automatic Gearbox          | ✓ |
| Heating seats              | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| Side rails                 | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |

## Removable element

|                 |   |
|-----------------|---|
| Spare wheel kit | ✓ |
| Load cover      | ✓ |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 |   |
|                 |   |

## Technical Document

|                         |   |
|-------------------------|---|
| User manual             | ✓ |
| Spare key               | ✓ |
| Remote key              | ✓ |
| Sat Nav CD ROM Software | ✓ |
|                         |   |
|                         |   |
|                         |   |
|                         |   |
|                         |   |
|                         |   |
|                         |   |
|                         |   |

## Tyres

|                                          |                                                                                     |                                                                                     |                                          |                                                                                       |
|------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|---------------------------------------------------------------------------------------|
| Bridgestone 215/65/17 All seasons 7.0 mm |  |  | Bridgestone 215/65/17 All seasons 7.0 mm |  |
| Bridgestone 215/65/17 All seasons 5.0 mm |  |  | Bridgestone 215/65/17 All seasons 5.0 mm |                                                                                       |

## Exterior

1



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Front left         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

2



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Back left          |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

3



|             |                  |
|-------------|------------------|
| Part        | Bumper           |
| Position    | Back             |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

4



|             |                    |
|-------------|--------------------|
| Part        | Wing               |
| Position    | Back right         |
| Damages     | Dent & Chips       |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Repair             |

5



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Back right         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

6



|             |                    |
|-------------|--------------------|
| Part        | Bonnet             |
| Position    | Front              |
| Damages     | Hail damaged       |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |