


Vehicle details

VIN	WVGZZZ5NZ LM020009	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	H3-71-PJ	Model	Tiguan Allspace 1.5 TSI DSG Highline Business R 5d	Maintenance mileage	-
Registration date	24/03/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	180 455 km	Engine size	1498	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	12/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Panoramic roof	✓
7 seater	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Load cover	✓
------------	---


Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Michelin 225/45/17 Winter 4.0 mm



Michelin 225/45/17 Winter 4.5 mm



Michelin 225/45/17 Winter 6.0 mm

Michelin 225/45/17 Winter 6.0 mm


Exterior

1



Part	Wing moulding
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

2



Part	Wing
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

3



Part	Exterior door mirror shell
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

4



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

9



Part	Door moulding
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

10



Part	Door moulding
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair