


Vehicle details

VIN	WVGZZZ5NZ LW358236	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	H2-03-LJ	Model	Tiguan 1.5 TSI ACT 110kW DSG Highline Bus. R 5d	Maintenance mileage	-
Registration date	06/03/2020	Year	2020	Exterior Color	Black Metallic
Odometer	124 561 km	Engine size	1498	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	17/03/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Rear parcel shelf	✓
-------------------	---


Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Continental 255/45/19 Winter 7.0 mm



Continental 255/45/19 Winter 7.0 mm



Michelin 255/45/19 Winter 6.0 mm

Michelin 255/45/19 Winter 6.0 mm

Exterior

1



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

2



Part	Wing
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

3



Part	Wing
Position	Back left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

4



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5



Part	Alloy wheel 19"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

6



Part	Alloy wheel 19"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair