



Volkswagen Tiguan: H547TV

Vinnumber:	WVGZZZ5NZLW380589	Versionname:	Tiguan 1.5 TSI ACT 110kW Comfortline Business DSG
First Registrationdate:	30/05/2020	Fiscalpower:	
Expertise Mileage:	86960	Power Kw:	110
Bodytype:		Body colour:	Deep Black pareleffect
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	599
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Lining Alcantara
Radio CD		Sun Roof electric
GPS		Panoramic roof
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Degree of wear

215/51/17/99 V				
Winter tyres:	Fr.L.	Vredestein: 5,2 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 7,2 mm
Tyre profile depth FL				5.2
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				7.2
Tyre size FL				215/51 R 17 99 V
Tyre size FR				215/51 R 17 99 V
Tyre size RL				215/51 R 17 99 V
Tyre size RR				215/51 R 17 99 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Door FL, Dent(s), Paintless dent repair



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)

