

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	273683
License plate	2ABK997
Vehicle identification number	WVGZZZ5NZMM046788
Dossier	2020 227 016
Make	Volkswagen Tig.Allsp.TDi 150 C
Mileage	112929.00
First registration	09/02/2021
	07/03/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
237	Wing Front right / Trim / Replace	N
40	Windshield // Repair	Y
117	Wing Rear Left / Trim / Replace	Y
134	Bumper Rear // Repair & Painting	N
231	Wing Front right // Smart Repair Medium	N
614	Front Left Door Interior Coating // Replace Completely	N


Damage Pictures



Wing Rear Left / Trim / Replace-scratch



Wing Front right // Smart Repair Medium-scratch + dent






Bumper Rear // Repair & Painting-scratch + dent



Windshield // Repair-cracked



Front Left Door Interior Coating // Replace Completely-Incinerated



Bumper Front // Painting-scratch



Wing Front right / Trim / Replace-scratch