



VOLKSWAGEN Tiguan: 2AMA117

Vinnnumber:	WVGZZZ5NZMW069099	Versionname:	Tiguan 2.0 TDI Active 90kW/122pk 5D/P Man-6
First Registrationdate:	10/05/2021	Fiscalpower:	
Expertise Mileage:	90814	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted):	N/A
Transmission:	Front	Parking lot:	d301
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	N/A		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Sun Roof electric
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Alarm		
Navigation with screen		
Airco electronic		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Degree of wear

215/65/17/99 V			
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.
	Re.L.	Hankook: 5 mm	Re.R.
Tyre profile depth FL			4.0
Tyre profile depth FR			4.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			215/65 R 17 99 V
Tyre size FR			215/65 R 17 99 V
Tyre size RL			215/65 R 17 99 V
Tyre size RR			215/65 R 17 99 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			260
Tyre make FR			260
Tyre make RL			260
Tyre make RR			260

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		

Roof liner, Scratch(es), Smart repair




Centre console, Scratch(es), Acceptable



Bumper spoiler F, Scratch(es), Smart repair



Bonnet, Scratch(es), Polish



Windscreen, Stone chip(s), Windscreen repair



Wing RL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Smart repair






Door FL, Dent(s) and scratch(es), Acceptable



Door trim RL, Scratch(es), Acceptable




Wing FL, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Smart repair



Bumper R, Scratch(es), Spot repair



Bumper moulding R, Scratch(es), Acceptable





Rear window, Scratch(es), Check



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Outside rear-view mirror base R, Scratch(es), Acceptable




Door FR, Dent(s) and scratch(es), Spot repair



Door trim FR, Scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Acceptable



Wing trim RR, Scratch(es), Acceptable

