



VOLKSWAGEN Tiguan

Tiguan 2.0 TDI SCR DSG

VIN NO WVGZZZ5NZNW023873

Registration Number NZNW023873



MOT Date

2027-02-01

Last Service

2025-10-14

Number of Owners

1

Last Service Mileage

149698

Number of Keys

2

First Registration Date

2022-03-09

Odometer Reading

184677 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250717093525
Inspection Date / Place	2025-07-17 / ARS Altmann AG Riedstadt	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	/Stoff Schwarz-Dunkelgrau	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Airbag Status	Anti-lock braking	Diesel particulate filter
Front parking sensors	Remote adjusting wing mirrors	Roof rails	Stability control
Leather steering wheel	Radio	Rear sunblind	USB Socket
Alloys wheels	Bluetooth telephone interface	Digital Radio	Heated wing mirrors
Remote central locking	Satellite navigation	Electrically folding wing mirrors	LED Headlamps
Rear parking sensors			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Extra Wheel / Tyre Set	Summer Tyres - Alloy	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6
Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4

Cosmetic Damage


11 Schäden



0 Schäden



Component		Damage	Comments
1	Windshield / Front	Paint / Chipping	
2	Hood	Bodywork / Dent / Dent	
3	Hood	Paint / Stone Chip	
4	Door / Front Left	Paint / Scratch / Scuff	
5	Door / Back Left	Paint / Scratch / Scuff	
6	Bumper / Back	Paint / Scratch / Scuff	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Rear Window / Back	Glass Break / Scratch / Scratch	
9	Tailgate	Bodywork / Dent / Dent	
10	Door / Back Right	Paint / Stone Chip	
11	Mirror / Front Right	Paint / Scratch / Scuff	



1. Windshield / Front
Paint / Chipping -



2. Hood
Bodywork / Dent / Dent -



3. Hood
Paint / Stone Chip -



4. Door / Front Left
Paint / Scratch / Scuff -



5. Door / Back Left
Paint / Scratch / Scuff -



6. Bumper / Back
Paint / Scratch / Scuff -



7. Bumper / Back
Paint / Scratch / Scuff -



8. Rear Window / Back
Glass Break / Scratch / Scratch -



9. Tailgate
Bodywork / Dent / Dent -



10. Door / Back Right
Paint / Stone Chip -



11. Mirror / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Other Equipments	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)