


## Vehicle details

|                   |                   |              |                                            |                           |           |
|-------------------|-------------------|--------------|--------------------------------------------|---------------------------|-----------|
| VIN               | WVGZZA1Z KV101824 | Brand        | VOLKSWAGEN                                 | Maintenance date          | -         |
| Licence Plate     | ZD-43-4P          | Model        | T-Roc 2.0 TSI 4Motion 140kW 7-DSG Sport 5d | Maintenance mileage       | -         |
| Registration date | 08/05/2019        | Year         | 2019                                       | Exterior Color            | Red Solid |
| Odometer          | 74 969 km         | Engine size  | 1984                                       | interior Color            | Grey      |
| Fuel              | Petrol            | Body Type    | -                                          | Next technical inspection | -         |
| Seats             | -                 | Transmission | Automatic                                  | CO2                       | -         |
| Doors             | 5                 | Gears        | -                                          |                           |           |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 17/01/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| Leather                    | ✓ |
| GPS system                 | ✓ |
| Alloy wheel rims           | ✓ |
| Automatic Gearbox          | ✓ |
| Tow                        | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| 4x4                        | ✓ |
| Side rails                 | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |
| Led lighting               | ✓ |


## Removable element

|                            |   |
|----------------------------|---|
| Spare wheel (wheel & tyre) | ✓ |
| Rear parcel shelf          | ✓ |

## Technical Document

|                         |   |
|-------------------------|---|
| User manual             | ✓ |
| Spare key               | ✓ |
| Remote key              | ✓ |
| Sat Nav CD ROM Software | ✓ |

## Tyres

|                                     |                                                                                     |                                     |                                                                                       |
|-------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
| Bridgestone 215/50/18 Summer 4.0 mm |  | Bridgestone 215/50/18 Summer 4.0 mm |  |
| Bridgestone 215/50/18 Summer 5.0 mm |  | Bridgestone 215/50/18 Summer 5.0 mm |  |

## Exterior

1



|             |                  |
|-------------|------------------|
| Part        | Bumper           |
| Position    | Front            |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

2



|             |                    |
|-------------|--------------------|
| Part        | Bumper             |
| Position    | Back               |
| Damages     | Dent & Chips       |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Repair             |

3



|             |              |
|-------------|--------------|
| Part        | Door         |
| Position    | Back right   |
| Damages     | Dented       |
| Severity    | Number > 2   |
| Repair mode | Smart Repair |

4



|             |              |
|-------------|--------------|
| Part        | Door         |
| Position    | Front right  |
| Damages     | Dented       |
| Severity    | Number > 2   |
| Repair mode | Smart Repair |

5



|             |                  |
|-------------|------------------|
| Part        | Wing moulding    |
| Position    | Front right      |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |