



Volkswagen T-Roc: H232DX

Vinnnummer:	WVGZZZA1ZLV075094	Versionname:	T-Roc 1.5 TSI 110kW Style Business DSG
First Registrationdate:	22/01/2020	Fiscalpower:	
Expertise Mileage:	93557	Power Kw:	110
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	755
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Radio CD		Central consol F
GPS		Luggage cover
Autom climate control		Front parking sensors
Windows electric F		Rear parking sensors
Radio multimedia		Tow bar removable

Degree of wear

215/55/17/94 V			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.
	Re.L.	Continental: 5,4 mm	Re.R.
			Continental: 5,3 mm
Tyre profile depth FL			6.0
Tyre profile depth FR			4.9
Tyre profile depth RL			5.4
Tyre profile depth RR			5.3
Tyre size FL			215/55 R 17 094 V
Tyre size FR			215/55 R 17 094 V
Tyre size RL			215/55 R 17 094 V
Tyre size RR			215/55 R 17 094 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Stain, Cleaning



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Wheel arch cover RR, Scratch(es), Replace



Wing RR, Scratch(es), Polish



Door RR, Chemical polution, Polish



Wing FR, Chemical polution, Polish



Bumper R, Scratch(es), Repair and paint (complete)





Rear window, Scratch(es), Replace



Tailgate / Boot, Chemical polution, Polish



Roof, Chemical polution, Polish

