



## Volkswagen T-Cross: G651XZ

Vinnnummer:	<b>WVGZZZC1ZLY050716</b>	Versionname:	<b>T-Cross 1.0 TSI 85kW Style DSG</b>
First Registrationdate:	<b>16/01/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>75821</b>	Power Kw:	<b>85</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Parking lot:	<b>1025</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>Yes</b>		

## Options

Number of keys total	<b>2</b>	Telephone equipment
Number keys remote	<b>2</b>	Lining semi-leather
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors

## Degree of wear

205/55/17 91 W				
Winter tyres:	Fr.L.	<b>Continental: 3,5 mm</b>	Fr.R.	<b>Continental: 2,1 mm</b>
	Re.L.	<b>Continental: 6,2 mm</b>	Re.R.	<b>Continental: 5,8 mm</b>
Tyre profile depth FL				3.5
Tyre profile depth FR				2.1
Tyre profile depth RL				6.2
Tyre profile depth RR				5.8
Tyre size FL				205/55 R 17 91 W
Tyre size FR				205/55 R 17 91 W
Tyre size RL				205/55 R 17 91 W
Tyre size RR				205/55 R 17 91 W
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

## Assistance equipment

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Service, Maintenance, Execute



Interior, Stain, Cleaning



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Cleaning



Door RR, Dent(s), Repair and paint (complete)



Wheel arch cover RR, Scratch(es), Replace



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Cleaning

