

## VOLKSWAGEN T-Cross T-Cross 1.0 TSI OPF

VIN NO WVGZZZC1ZMY051235 Registration Number 1ZMY051235



**MOT Date** 

**2**025-12-01

Last Service

**Number of Owners** 

**23:** 1

Last Service Mileage

**?** 

Number of Keys

**P**2

First Registration Date

**2**020-12-16

**Odometer Reading** 

**2** 69251 km

Country First Registered

Germany

### **Inspection Report Summary**

Customer	BCA Online	Report Number	P20250926121640
Inspection Date / Place	2025-09-26 / BCA Neuss	Cosmetic Grade	1

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	999
Engine Size	1.0	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	anthrazit	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Manual		

### Vehicle History & Documents

Service Book Available -	Next Service Mileage	km
Previous Usage	Imported	No
Manufacturer Warrenty		










































# Equipment

Tow ball	Alloys wheels	Bluetooth telephone interface	e Digital Radio
Heated wing mirrors	Remote central locking	Satellite navigation	Electrically folding wing mirrors
Radio	Airbag Status	Anti-lock braking	Cruise control
Front parking sensors	Remote adjusting wing mirrors	Roof rails	Stability control
Leather steering wheel	Rear parking sensors		

# **Equipment Details**


Right Rear Tyre Depth

Tow Ball Type	Static	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	16	Seat Heating	Front
Wheels & Tyres			
Right Front Tyre Depth	4	Left Front Tyre Depth	4

Left Rear Tyre Depth

## Cosmetic Damage

	Component	Damage	Comments
1	Fender / Back Left	Bodywork / Dent / Dent	
2	Tailgate	Bodywork / Dent / Dent	
3	Fender / Front Right	Paint / Scratch / Scuff	



1. Fender / Back Left Bodywork / Dent / Dent -

2. Tailgate Bodywork / Dent / Dent -



3. Fender / Front Right Paint / Scratch / Scuff -

#### **Mechanical Condition**

Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	<b>②</b>
Airbag Warning Light	•	Oil Pressure Warning Light	<b>⊘</b>
Brake Warning Light	•	Power Steering Warning Light	<b>②</b>
Alternator / Battery	<b>⊘</b>	No Dashboard Lights	•
Display Defect	•	Tire Pressure Monitoring System	<b>②</b>
Engine			
Engine Status / EML	•	Engine Leak Visible	<b>⊘</b>
Engine Starts	<b>⊘</b>		
Gearbox			
Gear Box	•		
Equipments Test			
Electric Windows	•	Navigation System	•
AC / Heating System	•	Main & Spare Keys Functioning	•
Parking Sensors / Cameras Functioning	<b>⊘</b>		
Levels			
Brakes Fluid	•	Coolant Fluid	

#### **Test Drive Inspection**

# Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** Clutch **Clutch Functioning** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

**User Guide** 

description.