



## Volkswagen ID.4: K325HH

|                         |                          |                        |                                   |
|-------------------------|--------------------------|------------------------|-----------------------------------|
| Vinnumber:              | <b>WVGZZZE2ZMP002750</b> | Versionname:           | <b>ID 4 150kW / 77kWh 1ST Aut</b> |
| First Registrationdate: | <b>22/12/2020</b>        | Fiscalpower:           |                                   |
| Expertise Mileage:      | <b>137230</b>            | Power Kw:              | <b>150</b>                        |
| Bodytype:               |                          | Paint type             | <b>Metalic</b>                    |
| Gearbox:                | <b>Automatic</b>         | Body colour            | <b>Mangan Grey metallic</b>       |
| Transmission:           | <b>4 Wheel-drive</b>     | Parking lot            | <b>42</b>                         |
| Fueltype:               | <b>Electric</b>          | Type of rims (mounted) | <b>Aluminium</b>                  |
| Number of seats         | <b>5</b>                 |                        |                                   |
| Maintenance needed      | <b>No</b>                |                        |                                   |
| Type of rims (mounted)  | <b>Aluminium</b>         |                        |                                   |

## Options

|                       |           |                            |
|-----------------------|-----------|----------------------------|
| Number keys remote    | <b>2</b>  | Rear parking sensors       |
| GPS                   |           | Headlights Xenon/LED/Laser |
| GPS storage           |           | Front parking sensors      |
| GPS storage           | <b>HD</b> | Lining artificial leather  |
| Number of keys total  | <b>2</b>  | Telephone equipment        |
| Windows electric F    |           | Luggage cover              |
| Radio multimedia      |           | Lining Alcantara           |
| Autom climate control |           | Roof rack                  |

## Tyres

| Location | Position | Measures                            | Depth  | Make     | Type   |
|----------|----------|-------------------------------------|--------|----------|--------|
| Front    | Left     | 255 / 45 / 20 / 105 / Y / Aluminium | 4,0 mm | Michelin | Summer |
|          | Right    | 255 / 45 / 20 / 105 / Y / Aluminium | 5,0 mm | Michelin | Summer |
| Rear     | Left     | 255 / 45 / 20 / 105 / Y / Aluminium | 4,0 mm | Michelin | Summer |
|          | Right    | 255 / 45 / 20 / 105 / Y / Aluminium | 4,0 mm | Michelin | Summer |

## Assistance equipment

|                                          |          |
|------------------------------------------|----------|
| Number of charging cables (rapid charge) | <b>1</b> |
| Number of charging cables (normal)       | <b>0</b> |

## Door FL, Dent(s) and scratch(es), Repair and paint (complete)



## Door RL, Scratch(es), Repair and paint (complete)



## Wing RL, Dent(s), Paintless dent repair



## Bonnet, Dent(s), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Replace

