

VW ID.4 PRO PERFORMANCE, 204HK, 2021

Vehicle information

License plate	FRS56J	Inspected by	C.C.
Year model	2021	Date of inspection	2025-03-04
Manuf. year/month	2021-04	City	Björkvik
First day in traffic	2021-05	Keys	2
Colour	Blå	Service book	Elektronisk servicebok
Mileage	94 890 km	Latest service	-
Fuel	EI (EV)	Mileage at the latest service	-
Transmission	Automat	Summer tires	21" alu-fälg 6/6/6/6
Engine effect	150 kW	Winter tires	alu-fälg dubbat 7/7/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Other, Other	Other	Saknas laddkablar	-
Door, Front left	Liten buckla/Repor		260 €
Door, Rear left	Repa/Repor		150 €
Bumper, Rear	Repa/Repor		260 €
Other, Other	Other	Saknas lock dragögla	-
Boot lid, Boot lid	Smart repair		70 €
Door, Rear right	Repa/Repor		150 €
Glass, Windshield	Stenskott/Spricka		-

Total excl. VAT	890 €
-----------------	-------

Images

[See all images in large format](#)























Dörr Vänster fram Liten buckla/Repor 3 500 kr



Dörr Vänster bak Repa/Repor 2 000 kr



Stötfångare Bak Repa/Repor 3 500 kr





Övrigt Övrigt Övrigt Saknas lock dragögla



Bagagelucka Bagagelucka Smart repair 1 000 kr



Dörr Höger bak Repa/Repor 2 000 kr





Glas Vindruta Stenskott/Spricka





