

Inspection Protocol



VW ID.4 PRO PERFORMANCE, 204HK, 2021

Vehicle information

License plate	YSM01T	Inspected by	A.H.
Year model	2021	Date of inspection	2025-04-10
Manuf. year/month	2021-05	City	Falkenberg
First day in traffic	2021-06	Keys	2
Colour	MÖRKGRÅMETALLIC	Service book	Elektronisk servicebok
Mileage	81 530 km	Latest service	-
Fuel	EI (EV)	Mileage at the latest service -	
Transmission	Automat	Summer tires	20" alu-fälg 5/6/6/5
Engine effect	150 kW	Winter tires	alu-fälg odubbbat 6/6/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Rims & Tires, Summer	Rim damage 1 wheel		110 €
Wing, Rear right	Dents below 30 mm		60 €
Door, Front right	Paint retouch traces		0 €
Bumper, Front	Chips, several		60 €
Bonnet	Chip		60 €
Glass, Windshield	Cracks (30-150 mm)		510 €
Rims & Tires, Summer	Rim damage 1 wheel	VB	110 €
Total excl. VAT			910 €

Service occasions

4000-MIL

Images

[See all images in large format](#)





















Fälgar & Däck Sommar Fälgskada 1 hjul 1 500 kr




Skärm Höger bak Bucklor under 3 cm 800 kr




Dörr Höger fram Lackbättring 50 kr




Stötfångare Fram Stenskott flertal 800 kr



Motorhuv Stenskott 800 kr



Glas Vindruta Sprickor (3-15 cm) 7 000 kr







Fälgar & Däck Sommar Fälgskada 1 hjul VB 1 500 kr

